



CERTIFICATE

Mr Krzysztof Drab,

attended the training, required by the distribution agreement, on May 27th, 2016 in our company in Markranstädt, Germany.


He had been instructed about dust measuring technology containing the following items:


- 1. General Overview and instructions concerning company's products**
- 2. Dust measuring principles**
- 3. Triboelectric dust measuring principle**
- 4. Instructions concerning the company's products**
 - 4.1. Extensive training on extractive dust measuring device PFM 06 ED**
 - 4.2. Special cases of application, installation and maintenance**


Dr. Födisch Umweltmesstechnik AG
Markranstädt
Zwenkauer Straße 159
04420 Markranstädt

Tel.: 034205 7550 • Fax: 034205 75540

May, 27th, 2016


Helmut Kaczmarek
Sales manager


Jürgen Krummsdorf
Research and Development



CERTIFICATE

Mr Maciej Jakubiak,


attended the training, required by the distribution agreement, on May 27th, 2016 in our company in Markranstädt, Germany.


He had been instructed about dust measuring technology containing the following items:

- 1. General Overview and instructions concerning company's products**
- 2. Dust measuring principles**
- 3. Triboelectric dust measuring principle**
- 4. Instructions concerning the company's products**
 - 4.1. Extensive training on extractive dust measuring device PFM 06 ED**
 - 4.2. Special cases of application, installation and maintenance**

Dr. Födisch Umweltmesstechnik AG
Markranstädt
Zwenkauer Straße 159
04420 Markranstädt

Tel.: 034205 7550 • Fax: 034205 75540
May, 27th, 2016


Helmut Kaczmarek
Sales manager


Jürgen Krummsdorf
Research and Development



CERTIFICATE

Mr Maciej Bernady,

attended the training, required by the distribution agreement, on May 27th, 2016 in our company in Markranstädt, Germany.

He had been instructed about dust measuring technology containing the following items:

- 1. General Overview and instructions concerning company's products**
- 2. Dust measuring principles**
- 3. Triboelectric dust measuring principle**
- 4. Instructions concerning the company's products**
 - 4.1. Extensive training on extractive dust measuring device PFM 06 ED**
 - 4.2. Special cases of application, installation and maintenance**

Dr. Födisch Umweltmesstechnik AG
Markranstädt
Zwenkauer Straße 159
04420 Markranstädt

Tel.: 034205 7550 • Fax: 034205 75540

May, 27, 2016

Helmut Kaczmarek
Sales manager

Jürgen Krummsdorf
Research and Development